UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

OPEN FILE REPORT 78-068

PLATE 6 OF 15

This report has not been edited for conformity with U.S. Geological Survey editorial standards or stratigraphic nomenclature.



EXPLANATION

1400
1390

STRUCTURE CONTOURS--Drawn on top of the coal bed. Contour interval is 10 feet (3.5m). Datum is mean sea level.

5
4

ISOPACH OF COAL BED--Showing thickness in feet. Isopach interval 1 feet (0.3m).

700

OVERBURDEN ISOPACH--Showing thickness of overburden, in feet, from the surface to the top of the coal bed. Isopach interval is 100 feet (30.5m).

5
1400
700

DRILL HOLE--Showing thickness of coal bed (upper number), elevation of the top of coal bed (middle number), and overburden from the surface to the top of the coal bed (lower number), all in feet.

To convert feet to meters, multiply feet by 0.3048

BASE FROM U.S. GEOLOGICAL SURVEY, 1970

COMPILED IN 1978



COAL RESOURCE OCCURRENCE MAP OF THE DODGE QUADRANGLE, DUNN AND MERCER COUNTIES, NORTH DAKOTA

BY
WOODWARD-CLYDE CONSULTANTS
1978

PLATE 6

ISOPACH, STRUCTURE CONTOUR AND OVERBURDEN MAP OF THE GARNER CREEK COAL BED